

Annual Inspection 2021

Date Inspected: 01-Aug-22
 By whom: Maria Hutson

Item	Inspection carried out, issues found.	Remedial Action Required	Action taken
------	---------------------------------------	--------------------------	--------------

Land

Kings Green	Checked for hazards and items requiring attention. Visual inspection of trees.	-	
Allotments	Checked for hazards and items requiring attention.	-	
Pathway between Joy Avenue and Dell Close	Checked for hazards and items requiring attention.	-	
Land at the top of Alan Avenue	Checked for hazards and items requiring attention. Some overgrowth, consider annual "tidy up"	Consider speaking with contractor regarding regular maintenance	

Signs

Village Sign and Mill Stone	Structure sound and slabs even.	-	
Allotment Sign	Sign in good condition.	-	
No Tipping Sign (Joy Ave/Dell Close)	Sign defaced but readable.	-	
SAM 2 and equipment	All seems to be working well.	-	

Item	Inspection carried out, issues found.	Remedial Action Required	Action taken
------	---------------------------------------	--------------------------	--------------

Dog Bins

Grove Road entrance to Playing Field	Checked for hazards and items requiring attention.	-	
Kings Green	Checked for hazards and items requiring attention.	-	
Blundeville Manor Entrance to Playing Field	Checked for hazards and items requiring attention.	-	
Alan Ave entrance to playing field	Checked for hazards and items requiring attention.	-	
St Mary's Close	Checked for hazards and items requiring attention.	-	
Church Road / School Road Junction	Checked for hazards and items requiring attention.	-	
Flordon Road (near Dell Close)	Checked for hazards and items requiring attention.	-	
Old Street	Checked for hazards and items requiring attention.	-	

Grit/Salt Bins

St Mary's Close 6 cu ft	Checked for hazards and items requiring attention.	-	
St Mary's Close 6 cu ft	Checked for hazards and items requiring attention.	-	
St Mary's Close 6 cu ft	Checked for hazards and items requiring attention.	-	
Alan Avenue 6 cu ft (play area)	Lid cracked but still useable. Look into prices for a replacement.	https://uk.glasdon.com/winter-safety-equipment/lockable-grit-	
Alan Avenue 6 cu ft (by social housing)	Checked for hazards and items requiring attention.	-	
Alan Avenue (grassed area)	Checked for hazards and items requiring attention.	-	
Alan Avenue (top end by Village Centre entrance)	Checked for hazards and items requiring attention.	-	
Flordon Road 6 cu ft	Checked for hazards and items requiring attention.	-	
Olive Avenue/Flordon Road 6 cu ft	Checked for hazards and items requiring attention.	-	

Item	Inspection carried out, issues found.	Remedial Action Required	Action taken
------	---------------------------------------	--------------------------	--------------

Grit/Salt Bins (cont.)

Church Road - Large 12 cu ft near Church	Checked for hazards and items requiring attention.	-	
Church Road 6 cu ft at A140 junction	Checked for hazards and items requiring attention.	-	
Dell Close	Checked for hazards and items requiring attention.	-	
Brightons Road / Longs Close	Checked for hazards and items requiring attention.	-	
Junction of Church Road and Grove Way	Checked for hazards and items requiring attention.	-	

Litter Bins

St Mary's Close	Checked for hazards and items requiring attention.	-	
St Mary's Close	Checked for hazards and items requiring attention.	-	
School Road	Checked for hazards and items requiring attention.	-	
A140 Bus Shelter	Checked for hazards and items requiring attention. No lid but not dangerous and still functional.	-	

Seating

St Mary's Close	Checked for hazards and items requiring attention.	-	
Kings Green	Checked for hazards and items requiring attention.	-	
Bus Shelter St Mary's Close	Checked for hazards and items requiring attention.	-	

Item	Inspection carried out, issues found.	Remedial Action Required	Action taken
------	---------------------------------------	--------------------------	--------------

Notice Boards

Lime Bank, Flordon Road	Checked for hazards and items requiring attention. Noted that board is checked by Cllr every time notices are posted.	-	
Adjacent to Bus Shelter, St Mary's Close	Checked for hazards and items requiring attention. Frame needs repair or replacement	Consider replacement, look into quotes	
School Road	Checked for hazards and items requiring attention.	-	

Bus Shelters

Ipswich Road	Checked for hazards and items requiring attention.	-	
St Mary's Close	Checked for hazards and items requiring attention.	-	